



Problems

turning direction is unclear

turning direction for the other side is different

the temperature has to be mixed every time

mixing is different in each season

Solution

